

DELHI JAL BOARD: GOVT. OF NCT OF DELHI  
OFFICE OF THE EXECUTIVE ENGINEER (RWH/GWC)  
ROOM NO. 209, VARUNALAYA PHASE-I  
KAROL BAGH, NEW DELHI - 110005

# 23558264

No./DJB/EE(RWH/GWC)/2019/3095  
To,

DATED: 27/6/19

The Principal,  
Tulips International School,  
611,612,613 Pooth Khurd,  
Delhi Bawana Road, Delhi-110039

Subject:-Regarding adequacy of rain water harvesting system at Tulips International School, 611,612,613 Pooth Khurd, Delhi Bawana Road, Delhi-110039.

Sir/Madam,

The above said unit has been inspected by Joint Inspection Team on dated 26.06.2019, constituted by Hon'ble NGT in O.A. No. 217/2016. It was found that three Nos. RWH pits with one No. old recharge well are existing at site.

The existing RWH structures are adequate to harvest the roof top run-off for catchment area of above said unit. The RWH structures were found to be functional at the time of inspection.

You are advised to keep the existing RWH system neat & clean & maintain the same periodically. Rain Water conveyance system shall be duly kept connected to RWH pits and filter media shall be maintained and kept neat & clean, as per DJB norms and over flow shall always remain connected to municipal drain.

*(Signature)*  
EE (RWH/GWC)

EE (RWH/GWC)  
DELHI JAL BOARD  
VARUNALAYA BHAWAN  
CHANDEWALAN, N.D.-5

For Tulips International School

*Sunita*

Manager